



CETRA 2018

5th International Conference on Road and Rail Infrastructure
17–19 May 2018, Zadar, Croatia

Road and Rail Infrastructure V

Stjepan Lakušić – EDITOR



Organizer
University of Zagreb
Faculty of Civil Engineering
Department of Transportation



CETRA²⁰¹⁸

5th International Conference on Road and Rail Infrastructure

17–19 May 2018, Zadar, Croatia

TITLE

Road and Rail Infrastructure V, Proceedings of the Conference CETRA 2018

EDITED BY

Stjepan Lakušić

ISSN

1848-9850

ISBN

978-953-8168-25-3

DOI

10.5592/CO/CETRA.2018

PUBLISHED BY

Department of Transportation

Faculty of Civil Engineering

University of Zagreb

Kačićeva 26, 10000 Zagreb, Croatia

DESIGN, LAYOUT & COVER PAGE

minimum d.o.o.

Marko Uremović · Matej Korlaet

PRINTED IN ZAGREB, CROATIA BY

“Tiskara Zelina”, May 2018

COPIES

500

Zagreb, May 2018.

Although all care was taken to ensure the integrity and quality of the publication and the information herein, no responsibility is assumed by the publisher, the editor and authors for any damages to property or persons as a result of operation or use of this publication or use the information's, instructions or ideas contained in the material herein.

The papers published in the Proceedings express the opinion of the authors, who also are responsible for their content. Reproduction or transmission of full papers is allowed only with written permission of the Publisher. Short parts may be reproduced only with proper quotation of the source.

Proceedings of the
5th International Conference on Road and Rail Infrastructures – CETRA 2018
17–19 May 2018, Zadar, Croatia

Road and Rail Infrastructure V

EDITOR

Stjepan Lakušić
Department of Transportation
Faculty of Civil Engineering
University of Zagreb
Zagreb, Croatia

ORGANISATION

CHAIRMEN

Prof. Stjepan Lakušić, University of Zagreb, Faculty of Civil Engineering
Prof. emer. Željko Korlaet, University of Zagreb, Faculty of Civil Engineering

ORGANIZING COMMITTEE


Prof. Stjepan Lakušić
Prof. emer. Željko Korlaet
Prof. Vesna Dragčević
Prof. Tatjana Rukavina
Assist. Prof. Ivica Stančerić
Assist. Prof. Maja Ahac
Assist. Prof. Saša Ahac
Assist. Prof. Ivo Haladin
Assist. Prof. Josipa Domitrović
Tamara Džambas
Viktorija Grgić
Šime Bezina
Katarina Vranešić
Željko Stepan

Prof. Rudolf Eger
Prof. Kenneth Gavin
Prof. Janusz Madejski
Prof. Nencho Nenov
Prof. Andrei Petriaev
Prof. Otto Plašek
Assist. Prof. Andreas Schoebel
Prof. Adam Szeląg
Brendan Halleman

INTERNATIONAL ACADEMIC SCIENTIFIC COMMITTEE

Stjepan Lakušić, University of Zagreb, president
Borna Abramović, University of Zagreb
Maja Ahac, University of Zagreb
Saša Ahac, University of Zagreb
Darko Babić, University of Zagreb
Danijela Barić, University of Zagreb
Davor Brčić, University of Zagreb
Domagoj Damjanović, University of Zagreb
Sanja Dimter, J. J. Strossmayer University of Osijek
Aleksandra Deluka Tibljaš, University of Rijeka
Josipa Domitrović, University of Zagreb
Vesna Dragčević, University of Zagreb
Rudolf Eger, RheinMain Univ. of App. Sciences, Wiesbaden
Adelino Ferreira, University of Coimbra
Makoto Fujii, Kanazawa University
Laszlo Gaspar, Széchenyi István University in Győr
Kenneth Gavin, Delft University of Technology
Nenad Gucunski, Rutgers University
Ivo Haladin, University of Zagreb
Staša Jovanović, University of Novi Sad
Lajos Kisgyörgy, Budapest Univ. of Tech. and Economics

Anastasia Konon, St. Petersburg State Transport Univ.
Željko Korlaet, University of Zagreb
Meho Saša Kovačević, University of Zagreb
Zoran Krakutovski, Ss. Cyril and Methodius Univ. in Skopje
Dirk Lauwers, Ghent University
Janusz Madejski, Silesian University of Technology
Goran Mladenović, University of Belgrade
Tomislav Josip Mlinarić, University of Zagreb
Nencho Nenov, University of Transport in Sofia
Mladen Nikšić, University of Zagreb
Andrei Petriaev, St. Petersburg State Transport University
Otto Plašek, Brno University of Technology
Mauricio Pradena, University of Concepcion
Carmen Racanel, Tech. Univ. of Civil Eng. Bucharest
Tatjana Rukavina, University of Zagreb
Andreas Schoebel, Vienna University of Technology
Ivica Stančerić, University of Zagreb
Adam Szeląg, Warsaw University of Technology
Marjan Tušar, National Institute of Chemistry, Ljubljana
Audrius Vaitkus, Vilnius Gediminas Technical University
Andrei Zaitsev, Russian University of transport, Moscow



IN-SERVICE PERFORMANCE OF ROAD CONCRETE BRIDGES – SET UP OF CASE STUDIES FOR NOVEL PRO-ACTIVE MAINTENANCE METHODOLOGY

Marija Kušter Marić¹, Jelena Bleiziffer¹, Anđelko Vlašić¹, Joško Ožbolt², Ana Mandić Ivanković¹, Mladen Srbić¹, Dominik Skokandić¹, Gordana Hrelja Kovačević¹, Nijaz Mujkanović¹, Stjepko Devald³, Danijel Tenžera⁴, Krunoslav Tepeš⁵, Mladen Burić⁶, Luka Lacković²

¹ University of Zagreb, Faculty of Civil Engineering, Croatia

² University of Stuttgart, Institute of construction material, Germany

³ Croatian Motorways Ltd., Croatia

⁴ Croatian Roads Ltd., Croatia

⁵ City of Zagreb, Croatia

⁶ County roads of Krapina-Zagorje County, Croatia

Abstract

Condition assessment of six bridges: Maslenica Bridge, Šibenik Bridge, Adriatic Bridge, Bridge of Youth, Homeland Bridge and Žeinci Bridge are presented in the paper. The bridges are of different type, age, material and traffic demands, but their in-service performance confirms steel corrosion in concrete as main deterioration cause. Influences of age, environment, climate and construction quality on bridge durability are analysed. The presented bridges will be used as case studies for proposed novel methodology of pro-active bridge maintenance based on visual inspection complemented with the non-destructive testing and application of numerical model for service life prediction.

Keywords: bridge, visual inspection, repair, condition assessment, corrosion

1 Introduction

The overwhelming majority of road bridges in Croatia are made of concrete: reinforced (RC) and prestressed (PC), while their main cause of deterioration is steel corrosion in concrete. Existing re-active maintenance policies based on visual inspection do not provide efficient and sustainable bridge management because corrosion induced damage and defects can be detected in advanced stage only. Hence new approach of pro-active maintenance of concrete bridges is proposed including visual inspection complemented with the non-destructive testing (NDT) and application of numerical model for service life prediction [1, 2]. Chosen NDT are simple yet cost efficient methods to evaluate (i) concrete quality and uniformity; (ii) concrete damage and crack geometry; (iii) concrete resistivity and (iv) reinforcement quantity and electrical potential [1, 2].

Numerical models for service life prediction of RC structures have been developed and subsequently improved in the last three decades. Recently developed 3D chemo-hygro-thermo mechanical (3D CHTM) model is one of the most comprehensive models for realistic simulation of transport and corrosion processes before and after depassivation of reinforcement bar in concrete taking into account damage in concrete caused by mechanical loads [3-8]. The 3D CHTM model has proved its ability for realistic simulation of mechanical and corrosion processes on several case studies [9]. However, quantifying the material, mechanical and corrosion

related parameters and their interactions are still challenging tasks and main objective of the current research project. Application of the 3D CHTM model on existing bridges will contribute to the development of engineering models and formulation of design rules in order to increase the durability of structures and reduce their maintenance costs.

Table 1 Basic data on case studies

| Bridge name | Bridge type | Road authority | Opened to traffic |
|------------------|--|--|-------------------|
| Maslenica Bridge | RC deck arch Superstructure: prestressed continuous T girders + RC slab | Croatian Motorways | 1997 |
| Šibenik Bridge | RC deck arch Superstructure: prestressed simple supported T girders + transversely prestressed slab | Croatian Roads | 1966 |
| Žeinci Bridge | RC tied arch Superstructure: grillage system of longitudinal and transverse beams | County roads of Krapina-Zagorje County | 1913 |
| Adriatic Bridge | Prestressed continuous I girder + RC slab | City of Zagreb | 1981 |
| Bridge of Youth | Composite continuous girder: steel box girder + RC slab | City of Zagreb | 1974 |
| Homeland Bridge | Externally prestressed continuous box girder + transversely prestressed slab | City of Zagreb | 2006 |




Figure 1 Case studies – bridges layouts

The proposed methodology will be demonstrated on six concrete road bridges of different type, age, material and traffic demands; managed by four different road authorities (Table 1, Figure 1). Maslenica and Šibenik Bridge are exposed to maritime environment, while other

bridges are located in continental climate and exposed to de-icing agents during winter period. The oldest among them is Žeinci Bridge, built 105 years ago. Lower exposure to chlorides and reduced traffic demands have contributed to its long life. Unfortunately, there is no available data on design, construction and maintenance of this bridge; hence its overall condition assessment will be given after detailed visual inspection and NDT, planned to be conducted within the current research project [2]. Condition assessment of other five bridges, with available data on maintenance programme, will be provided in next chapter in order to evaluate vulnerability to reinforcement corrosion.

2 Case studies: condition assessment

2.1 Maslenica Bridge

Bridge visual inspection, measuring concrete cover, determining surface hardness by rebound hammer, concrete compressive strength and elasticity modulus on taken samples, as well as chloride content and gas permeability were carried out in 2006 [10]. The results were compared to initial (laboratory) testing from 1995-1996, which showed higher compressive strength than design value, and lower permeability due to continued hydration process and carbonation [11]. Detailed visual inspection of all structural members accompanied by chloride content measurements was conducted in 2010 [12]. It was concluded [13] that the bridge is in good condition; however, there is some localized damage with the areas of exposed corroded reinforcement on arch abutment columns assessed as requiring immediate repair and protection. The concrete cover depth at those locations was smaller than 5 cm prescribed in bridge design specifications. Determination of chloride content was carried out on the total of 120 specimens taken from 24 locations distributed among the arch abutments, the arch itself, the arch abutment columns and the superstructure showing uneven distribution of chloride content, depending on the location from which the specimen was taken, with higher content and deeper penetration on the surfaces facing north.

The testing programme was amended in 2012 [14] with testing concrete strength and homogeneity of concrete, determining the location of reinforcing bars and concrete cover depth, carbonatization depth, adding new positions for chloride content measurements, identifying crack patterns and widths and delamination zones, determining mechanical and chemical properties of concrete and




Figure 2 Repair of Maslenica Bridge after 20 years of service

reinforcing steel, testing concrete permeability (to gases, water absorption, chloride migration / diffusion). Those tests were determined as necessary for developing an appropriate repair design. It was concluded that the concrete compressive strength is approximately 20 % higher than prescribed in design specifications. Unfortunately, the testing related to concrete permeability showed poor results and the chloride content was above critical (0.4 % of cement mass) at approximately 20 % of concrete surfaces.

The repair has started in spring 2016 with 2 types of repair solutions employed depending on the results of corrosion risk assessment [14]. Structural members for which corrosion is

assessed to be still in its initiation period (arch, external main girders, all columns except those at the arch springing up to 35 m a.s.l.) are repaired by corrosion inhibiting impregnation, structural repair mortar and protective coating. Type 2 repair (for columns at the arch springing up to 35 m a.s.l. and arch abutments) includes repair with high strength micro reinforced concrete (with increase of concrete cover depth on columns), subsequently applying surface protection.

At the same time, an effort was made [14] to put in operation corrosion monitoring system installed during bridge construction. 16 corrosion sensors were found to be installed adequately, and subsequently 19 were used for measurements [15].

2.2 Šibenik Bridge

An inspection of Šibenik Bridge carried out in 1989 revealed [16] very poor condition of the superstructure due to water seepage through the joints that have opened in the asphalt as there was no waterproofing layer. Immediate repair was requested, but was not carried out. Detailed inspection was then undertaken in 1995 [16] including NDT of concrete mechanical properties (4 locations), measurements to assess the condition of embedded reinforcing and prestressing steels (crack width measurements by microscope and ultrasonic testing, corrosion potential measurements and check of prestressing tendons by endoscope at 2 locations), determination of concrete compressive strength, chloride content and carbonatization depth (11 specimens from 4 locations), confirming earlier conclusions. The bridge was also damaged by missiles during the War in 1990s (to the arch and the superstructure), which were repaired (est. 1996). In 1985 a finger expansion joint was installed, and the other in 1999, when some repairs on sidewalks were also carried out [17]. Another thorough inspection was in 2005 [16, 18] when chloride ingress and concrete cover testing at 20 locations was carried out showing that the process of corrosion started at the arch abutment on Šibenik side. Geodetic measurements were also conducted at the time as the bridge, constructed by suspended cantilever technique, has in the first 10 years of its service experienced substantially larger creep and shrinkage deformations than expected by the design.

The inspection and testing from 2005 were the basis for repair design. The repair was completed in 2012. It included [19] removing the asphalt layer, placing the waterproofing and new courses with elastic expansion joints at all supports (except at locations of finger joints), complete reconstruction of sidewalks (with lightweight aggregate concrete) and curbs, and repair to cornice, railings and existing expansion joints. Drainage was improved by adding new gutters. The work had to be executed carefully as the roadway slab is transversely prestressed. The repair of the main and cross girders focused to the area close to the supports: poor concrete was removed by water under pressure; the reinforcement appropriately cleaned, amended and protected; and repair mortar applied. The same procedure was used to repair the underside of cantilevers carrying the sidewalks. Localized damage found on all elements was also repaired. External concrete surfaces were subsequently protected with corrosion inhibiting impregnation and crack bridging and anti-carbonation protective coating. The repair of the structure that connects the superstructure and the arch at its crown was treated separately, as large number of wide cracks appeared. This part of structure was thus additionally inspected in detail in 2009 [20]. Finally, the repair design [21] stipulated injection of all cracks and repair using structural repair mortar, as well as subsequently applying surface protection.

2.3 Bridge of Youth

The last main inspection of Bridge of Youth was carried out in 2017 [22] for the whole bridge comprising two viaducts and the main bridge. This comprehensive inspection included investigative work to determine the condition of concrete. South east part of the approach viaduct was rehabilitated in 2010 due to reinforcement corrosion. Inspection determined that most of

the bridge is structurally and functionally not compromised. Maintenance work is recommended for restoration of bridge equipment such as drainage, and restoration of corrosion protection. Expansions joints and bearings show most damage, they are to be replaced. Reinforced concrete shows signs of reinforcement corrosion in sidewalks part of the deck, with concrete protective layer cracking and delamination, these are to be repaired. Deck waterproofing does not exist; it needs to be placed during next asphalt replacement. Some of the columns steel envelope is corroded and detached from concrete. The worst condition of the bridge is in its central and west part of the south approach viaduct. This part needs immediate repairs and partly replacement of concrete deck and cantilevers and replacement of the sidewalks, cornice and repairs on parts of the columns.

2.4 Adriatic Bridge

The last main inspection of Adriatic bridge was carried out in 2017 [23] for the whole bridge comprising two viaducts and the main bridge. During inspection, investigative work was done to determine chloride level and strength in concrete. Critical chloride level was determined across 4 cm depth in columns S1, hence these elements need to be repaired. Inspection determined that the damage to structural parts of the bridge are of such a scope that the bearing capacity of the bridge is reduced. The damage is as follows: sidewalks cantilevers concrete delamination due to reinforcement corrosion, asphalt cracking, curb damage, railing corrosion, cornice delamination and cracking, expansion joints blockage, main girders severe reinforcement corrosion and concrete cracking, drainage clogging, columns and abutments reinforcement corrosion, bearings corrosion and misalignment, cracking of concrete bearing pedestals. Box girders of the main central part of the bridge over Sava River are heavily damaged due to reinforcement corrosion, with large parts of the concrete protective layer missing and reinforcement area significantly reduced. Drainage leakage inside box girders is recorded with fills of mud and water. South abutment is severely damaged from water leakage and reinforcement corrosion, with bearings damage. Recommendation is given for the need of extensive rehabilitation.

2.5 Homeland bridge

Repair work on Homeland Bridge was performed in 2012 focusing on rehabilitation of the cable stay anchors due to problems of inadequate drainage around them, which caused water to leak around the anchors inside the box girder. Rehabilitation comprised new waterproofing and concrete layer for inclination towards drains. Main inspection of Homeland bridge was carried out in 2017 [24] and it was concluded that the structure is in good condition. Some minor local cracking around anchor beams was noticed, which is to be monitored for the next 5 years. Cable stay deviators exhibit moderate cracking, but without signs of reinforcement corrosion. Most severe damage was noticed around previously rehabilitated cable stay anchors: water is still leaking around anchor pipe protection inside the box girder, hence new rehabilitation is recommended. Bridge substructure is in relatively good condition. Some cracking is recorded on the abutment foundation plate which should be sealed with injecting. Repairs are needed on most of drains which are clogged through the bridge, and some drainage pipes, to avoid further damage from water.

3 Conclusion

Presented case studies confirm chloride induced corrosion of steel in concrete as main cause of bridge deterioration. Older bridges require greater intervention in maintenance during the fourth and fifth decades of their service life in order to achieve the designed service life of 100 years, e.g. Šibenik Bridge has been recently repaired, while repair of Adriatic Bridge and

Bridge of Youth are in plan. Environment and climate significantly affect bridge durability, contemporary Maslenica Bridge on Adriatic Coast is the most vulnerable to reinforcement corrosion because of aggressive maritime environment with unfavourable combinations of sea salt and strong winds resulting in complex repair after 20 years of service. On the other hand, less use of de-icing agents over the past century contributed to achieving a service life of over 100 years for Žeinci Bridge. Construction quality has important role for bridge durability, since only high-quality and uniform concrete provides sufficient protection for the steel from corrosion, while concrete cracks and damage, inadequate water drainage and lack of waterproofing accelerate deterioration processes. The youngest among the case studies, Homeland Bridge was repaired six years after construction in order to fix errors and imperfection made on site.

Re-active maintenance policy, based on interventions once the bridge is obviously in critical condition, results in lower performance of structures and higher overall costs. In order to achieve efficient and sustainable bridge management new approach of pro-active maintenance of concrete bridges is proposed including visual inspection complemented with the NDT and application of numerical model for service life prediction. Data obtained on the bridges will be used for calibration of the 3D CHTM model in order to precisely predict the remaining service life as a prerequisite for sustainable life cycle cost analysis.

Acknowledgments

This research was carried out in the framework of the UKF project No 04/17 “Influence of concrete damage on reinforcement corrosion – computer simulation and in service performance of bridges” (CODEbridges) supported by Unity through Knowledge Fund.

References

- [1] Kušter Marić, M., Ožbolt, J., Mandić Ivanković, A. et al.: Quality specification for concrete bridges vulnerable to reinforcement corrosion, The seventh workshop of COST Action TU1406 “Quality specifications for roadway bridges, standardization at a European level”, in press, Wroclaw, Poland, 1-2 March 2018.
- [2] Influence of concrete damage on reinforcement corrosion – computer simulation and in service performance of bridges (CODEbridges), www.grad.unizg.hr/codebridges, 09.03.2018.
- [3] Ožbolt, J., Balabanić, G., Periškić, G., Kušter, M.: Modelling the effect of damage on transport processes in concrete. *Construction and Building Materials*, 24, pp. 1638-1648. <https://doi.org/10.1016/j.conbuildmat.2010.02.028>, 2010.
- [4] Ožbolt, J., Balabanić, G., Kušter, M.: 3D numerical modelling of steel corrosion in concrete structures. *Corrosion Science*, 53, pp. 4166-4177. <https://doi.org/10.1016/j.corsci.2011.08.026>, 2011.
- [5] Ožbolt, J., Oršanić, F., Balabanić, G., Kušter, M.: Modeling damage in concrete caused by corrosion of reinforcement: coupled 3D FE model. *International journal of fracture*, 178 (1), pp. 233-244. <https://doi.org/10.1007/s10704-012-9774-3>, 2012.
- [6] Ožbolt, J., Oršanić, F., Balabanić, G.: Modeling influence of hysteretic moisture behavior on distribution of chlorides in concrete, *Cement and Concrete Composites*, 67, pp. 73-84. <https://doi.org/10.1016/j.cemconcomp.2016.01.004>, 2016.
- [7] Ožbolt, J., Oršanić, F., Balabanić, G.: Modeling corrosion-induced damage of reinforced concrete elements with multiple-arranged reinforcement bars. *Materials and Corrosion*, 67, pp. 542–552. [doi:10.1002/maco.201508569](https://doi.org/10.1002/maco.201508569), 2016.
- [8] Ožbolt, J., Balabanić, G., Sola, E.: Determination of critical anodic and cathodic areas in corrosion processes of steel reinforcement in concrete. *Materials and Corrosion*, 68: 622–631. [doi:10.1002/maco.201609295](https://doi.org/10.1002/maco.201609295), 2017.

- [9] Kušter Marić, M., Ožbolt, J., Balabanić, G., Mandić Ivanković, A., Zarić, D.: Service life prediction of concrete structures in maritime environment – case study: Maslenica Motorway Bridge, 1st Int. Conf. on Construction Materials for Sustainable Future, pp. 629-636, Zadar, Croatia, 19-21.04.2017.
- [10] Report on quality testing of concrete built-in Maslenica Bridge (Project: Durability of reinforced concrete structures in maritime environment – TABKIMO), University of Zagreb, Faculty of Civil Engineering, Zagreb, 2007. (in Croatian)
- [11] Stipanovic, I., Bjegovic, D., Mikulic, D., Serdar, M.: Time dependent changes of durability properties of concrete from Maslenica Bridge at the Adriatic Coast, Integral Service Life Modelling of Concrete Structures, Bagnaux: RILEM Publications S.A.R.L., 2007, pp. 87-95.
- [12] Maslenica Bridge, Report on main inspection of the bridge, Institut IGH, d.d., Zagreb, 2011. (in Croatian)
- [13] Bleiziffer, J., Mavar, K., Ille, M., Škarić Palić, S., Dimić Vuković, S., Balagija, A.: Condition assessment of the Maslenica highway bridge, 3rd Chinese-Croatian Joint Colloquium Sustainable Arch Bridges, pp. 309-316, Zagreb, Croatia, 15-16 July 2011.
- [14] Repair and protection of concrete structure of Maslenica Bridge, design documents, Institut IGH, d.d., Zagreb, 2014. (in Croatian)
- [15] Sekulić, D., Serdar, M.: Experience with corrosion monitoring using embedded sensors in three bridges on the Adriatic Coast, 1st Int. Conf. on Construction Materials for Sustainable Future, pp. 614-636, Zadar, Croatia, 19-21.04.2017.
- [16] Report on main inspection of Šibenik Bridge on road D-8, Vol. 1-4, Croatian Institute for Bridge and Structural Engineering, Zagreb, 2005. (in Croatian)
- [17] Šibenik Bridge damage repair will not be completed before the 50-day deadline, repair works to last until 5 November, Slobodna dalmacija, 21.10.1999. (in Croatian).
- [18] Medak, M., Radić, J., Veverka, R., Bleiziffer, J., Kučer, A., Kalafatić, I.: Main inspection of Šibenik arch bridge, Int. Conf. on Bridges, pp. 961-968, Dubrovnik, Croatia, 21-24.05.2006.
- [19] Amendments to the repair design of Šibenik Bridge, Croatian Institute for Bridge and Structural Engineering, Zagreb, 2010. (in Croatian)
- [20] Report on special inspection and testing of the structure at the arch crown of Šibenik Bridge, Empora d.o.o., Dubrovnik, 2009. (in Croatian)
- [21] Repair design of the structure at the arch crown of Šibenik Bridge, Empora d.o.o., Dubrovnik, 2009. (in Croatian)
- [22] Main six-year inspection report of Youth Bridge, Institute I.G.H. d.d., Zagreb, 2017. (in Croatian)
- [23] Main six-year inspection report of Adriatic Bridge, Geoexpert-I.G.M. d.o.o., Zagreb, 2017. (in Croatian)
- [24] Main six-year inspection report of Homeland Bridge, Ascon Institut d.o.o., Zagreb, 2017. (in Croatian)

